



Location: North of Vinne Ha Ha Boat Landing

Date: 2-11-03

Photo of frozen sediment “heave”. This area is an area of lake bed that was desiccated during the winter drawdown and appears to have frozen and is acting like an ice sheet heaving close to the normal shoreline.



Location: North of Vinne Ha Ha Boat Landing

Date: 2-11-03

Photo of frozen sediment “heave”. This is a close-up of the frozen sediment layer heaving up. Width of frozen sediment about 4 inches thick.



Location: West of Bingham Road Boat Landing

Date: 2-11-03

Photo of frozen sediment “heave” along exposed sediments below the normal water level elevation. Arrow depicts location of normal summer water level (@776.20 msl). Note heave action has moved the steel post in center of photo shoreward.



Location: West of Bingham Road Boat Landing
Photo of frozen sediment “heave”.

Date: 2-11-03